






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Reservju daļu



Position




- | | |
|-------------------|-------------------|
| 1 = A 963 131 NU | 22 = A 962 391 XX |
| 4 = A 963 132 NU | 23 = A 962 368 NU |
| 8 = A 963 143 NU | 24 = A 962 384 XX |
| 9 = A 963 146 NU | 25 = A 960 895 NU |
| 10 = A 963 147 NU | 26 = A 960 896 XX |
| 13 = A 962 594 NU | 27 = A 961 659 NU |
| 15 = A 960 890 NU | 29 = A 962 388 XX |
| 16 = A 960 706 NU | 30 = A 962 870 XX |
| 17 = A 960 891 NU | 32 = A 962 872 XX |
| 18 = A 960 898 NU | 33 = A 960 704 NU |
| 19 = A 960 899 NU | A 962 476 NU |
| 20 = A 963 564 NU | 34 = A 960 705 XX |
| 21 = A 963 427 NU | |

XX = AA, AD...








CERATHERM 100
A 4659 ..

1110 / A 866 148 40
 (+ A 865 612)
 Made in Germany



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





	P	bar		MAX. 10		5		Q (3 bar)
	T	°C		MAX. 80		65 55		l/min 30