







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Zapczęści / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi


Pos.	Part No.
1	A 861 545 AA
2	A 861 371 NU
3	A 861 375 NU
4	A 861 376 NU
5	A 861 549 NU
6	A 861 372 NU
7	A 861 546 NU
8	A 861 169 AA
9	A 861 547 AA




 Ideal Standard


CERATHERM C100
 A 7538 ..






1021 / A 868 970
 Made in Germany



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





	P	bar		MAX. 10		5		Q	(3 bar)
			0,5						l/min
	T	$^{\circ}\text{C}$		MAX. 80		65			22
						55			20